MARYLAND GEOLOGICAL SURVEY Merryman Hall The Johns Hopkins University Baltimore, Maryland 21218 (301) 235-0771

COUNTIES (MD/PA)	WASHINGTON/FRANKLIN
M&D milestone no	93 (96)
MHT-HSI no.	WA-IV-093
	•

PROTECTED SANDANGUBEDY/AXISSIMIX

FIELD SHEET: MASON & DIXON LINE, MARYLAND-PENNSYLVANIA BOUNDARY MARKER SURVEY

LOCATION: USGS 7.5'quadrangle Smithsburg 1953 original site // MANKACA/date 1767

Off S/S Harbaugh Church Road, Midvale, PA. About 2 miles W of the village of Pen Mar, at a point about 700' E of MD-418/Midvale Rd & about 200' S of Harbaugh Church Rd; opposite the Martin house, in the middle of a level, farmed field. Can be seen from Harbaugh Church Rd when vegetation is dormant.

DIRECTIONS TO SITE:

From M&D 92 (95): continue W/on old Pen Mar Rd to its end at Harbaugh Church Rd; bear left (W) & continue about 0.75 mile past Harbaugh Church to Martin house on N/S (a 2-story log house covered with asbestos shingles). Ask Martins' (over)

DESCRIPTION/MEASUREMENTS: original/replican/replacement/date 1767; oolitic limestone post, about 1' square, standing about 1' above ground; P on N/S, M on S/S
N face (PA): 12% wide x 16" high; P & circle panel distinct; some fluting & margins remain; chips top corners & edges

E face: 11" wide x 14" high; most fluting & margins distinct; chips top corners & edges

11" wide x 15" high; most fluting & margins distinct; chips top corners & edges

11" wide x 15" high; most fluting & margins distinct; chips top corners & edges

11" wide x 15" high; most fluting & margins distinct; chips top corners & edges

11" wide x 15" high; most fluting & margins distinct; chips top corners & edges

11" wide x 15" high; most fluting & margins distinct; chips top corners & edges

11" wide x 15" high; most fluting & margins distinct; chips top corners & edges

11" wide x 15" high; most fluting & margins distinct; chips top corners & edges

11" wide x 15" high; most fluting & margins distinct; chips top corners & edges

12" wide x 15" high; most fluting & margins distinct; chips top corners & edges

12" wide x 15" high; most fluting & margins distinct; chips top corners & edges

12" wide x 15" nigh; most fluting & margins distinct; chips top corners & edges

12" wide x 15" nigh; most fluting & margins distinct; chips all top edges bench mark:

CONDITION OF MARKER/FOUNDATION: excelbent/good/fair/deteriorated/rhins/unexposed/1900-03 Resurvey notes (order no. 96), as in MGS Vol. 7, 1908, p.89
96. Milestone No. 93, M. & D., 1767. In a fence line, near Midvale, Pa.

1950 Inspection notes (present order no.94, photo no.93) as in Bayliff, 1959, Appendix C, p. 103

96. Original monument in solid foundation; good condition. Chipped on all sides at top; chipped on southwest corner.

1979-81 Inspection notes: order no. 93 (96); photos/negatives/slides no. 93 (96) 93 (96). Original M&D milestone of 1767 in place, in good condition, firmly set. Letters and most embellishments distinct and intact. Large chips top edges and corners. Protected by owners, but vulnerable to damage by farm machinery.

SURROUNDING PROPERTY OWNERS (MD/PA): names, addresses, phones MD: tax map 13, block 22, P. 32, deed 290 /284, acres 72.75 Mildred H. Martin, Rt. 3, Box 305, Smithsburg, MD 21783

PA: tax map , block , P. , deed / Phone: 301/ Mildred H. Martin

RECORDED BY: names, addresses, phones, dates Alice Martin 2/15/81
14308 Mount Ave., Phoenix, MD 21131 Phone: 301/472-2128
Assisted by Clyde E. Martin

Also see: reverse side χ , B&W photos χ , negatives χ , color slides χ , maps χ , MHT-HSI form , other

DIRECTIONS TO SITE, continued

permission to cross property & inspect monument. Park on S/S of Rd at grassy entrance to old farm service lane. Cross over stream here, on bridge. Stone is about 250' SE from this point. Fence (mentioned in Resurvey notes) has been moved to N/S of stream.

NOTES

Both Mr. & Mrs. Martin were very hospitable and would appreciate having a copy of the information about their stone when assembled. Their farm extends some 185 acres (both sides of Harbaugh Church Road), and includes the old family place (last house on N/S, a very old brick house probably built early 1800's, along with old stone wash house). This house was vacant when we were there, but is ordinarily used for their tenant farmer.

As with many other MD-PA boundary monuments in the middle of cultivated fields: MGS will want to make arrangements for marking this monument so as to prevent further chipping by farm machinery. Most such damage is inadvertent, especially in corn fields where the monument is completely hidden during the growing season. Horace Waybright of Frederick County (M&D 78) solved this problem by a tail pipe with flag--tall enough to be seen above any crops.

B&W PHOTOS/NEGATIVES

5x7 NE corner (1981.2.10), Alice Martin 2/15/81

5x7 SW corner (1981.2.13), "

3½x5 View N: of stone, Harbaugh Church Rd & Martin farmhouse (1981.2.14),
Alice Martin 2/15/81

COLOR SLIDES

2x2 NE corner (1981.1.8), Alice Martin 2/15/81

2x2 SW corner (1981.1.10), "

2x2 View N: of stone, Harbaugh Church Rd & Martin farmhouse (1981.1.9), Alice Martin 2/15/81

MAPS

USGS 7%' topographic quadrangle section 1900-03 Resurvey engineer's map (Plates XXXV & XXXVI) MD tax map section

OTHER



MA-TV-093
MAGORIE DINON WEST LINE: MILESTONE 93(96)

MAGONE DIXON WEST LINE! HILLSTONE 93(96)
SW CORNER (- 11) LOOKING- FOR ALD
HARBAUCH CHURCH LIE MARTIN BAKN

PACTO: ALICE HARTIN 1981.2.13 2/15/81



WM-1K-093 MES MID WESTLINE : MILESTONE 93(96) S/S OF STONE, LOOKING N ACROSS HARBAUGH CHURCH RD E MAUTIN HARMHOUSE PHOTO: ALICE MARTIN (1981.2.14. 2/15/34



WA-TT 192 MES MARINE MARITERS LETERE 13 96) AL CULLER (- 11) FROM ALICE MARTIN (1981.2.15) 2/15/10



